


Digital tuning problems with SONY Bravia KDL-32L4000

NOTE: The antenna signal is around 65% of quality.

1 – Menu



2 – Then Setup




3 – Digital installing





4 – Automatic digital tuning





5 – No digital channels were found in automatic tuning







6 – Manual Digital tuning on 56 channel (Portuguese Digital Tv)



7 – Five channels found (Portuguese Channels), please see especial characters after the channel name (Channels, RTP1, RTP2, SIC, TVI)



8 – I choose to save Channels



9 – When I go to the Digital channels no digital chaneles were saved.

Programas não guardados

000
DIGITAL

